



Universal Wax Warmer Liners



Item #303402

TNG Worldwide • New Hudson, MI 48165

tngworldwide.com • 800.520.6000

©2021 TNG • Made in China

IMPORTANT INSTRUCTIONS — RETAIN FOR FUTURE USE

Thank you on your purchase of **Too Naked Universal Wax Warmer Liners**. You will enjoy the total ease of use, convenience, hygiene for each client and freedom to use wax anywhere.

The patent-pending liner is made of sturdy HDPE plastic with specially designed ridges to prevent liner from melting while allowing the wax beads to melt uniformly.

Please follow these simple instructions for use:

Instructions For Use:

1. Insert Too Naked Universal Wax Warmer Liner into Too Naked Wax Warmer. See Fig. 1.
2. Add Too Naked Strip-Free beads or wax beads of your choice.
3. Turn wax warmer dial to high for 20 minutes, stirring beads as needed. See Fig. 2.
4. After 20 minutes turn dial to "Bead" setting or if using a different warmer, set dial before Medium setting. See Fig. 3. Allow up to 20 minutes for wax beads to turn into smooth consistency for waxing.
5. Once melted to proper consistency use as directed. See Fig. 4. Can be removed from warmer for up to five minutes.

Precautions:

If not using Too Naked Wax Warmer, temperature settings may differ so test and adjust thermostat as needed. Wax beads melt at temperatures ranging from 104°F to 112°F. Do not overheat.

If for any reason you have questions or issues, please contact us toll-free 800-520-6000.

Fig 1.



Fig 2.




Fig 3.




Fig 4.

